



Photo 1 – Wreckage from Front (Photo Courtesy of FAA)



Photo 2 – Damage to Fuselage (Photo Courtesy of FAA)



Photo 3 – Tailwheel and Springs (Photo Courtesy of FAA)



Photo 4 – Tailwheel and Springs (Photo Courtesy of FAA)