



Photo 1 – Main Wreckage, View of Right Side (FAA Photo)



Photo 2 – Main Wreckage, View from Front (FAA Photo)



Photo 3 – Main Wreckage, View from Right Side (FAA Photo)



Photo 4 – Right Wing Damage (FAA Photo)



Photo 5 – Forward Fuselage (FAA Photo)



Photo 6 – Aircraft Cockpit (FAA Photo)



Photo 7 – Lower Fuselage (FAA Photo)



Photo 8 – Forward Engine Compartment and Propeller (FAA Photo)



Photo 9 – Main Wreckage, Top View (FAA Photo)



Photo 10 – View of Upper Fuselage (FAA Photo)