



Photo 1 – Helicopter at Accident Site, From Right (Photo Courtesy of FAA)



Photo 2 – Helicopter from Front (Photo Courtesy of FAA)



Photo 3 – Helicopter from Right (Photo Courtesy of FAA)



Photo 4 – Damaged Number 2 Bearing (Photo Courtesy of FAA)



Photo 5 – Damaged Number 2 Bearing, Removed (Photo Courtesy of FAA)