



Photo 1 – Damaged left wing (courtesy of McLarens claim Serv.)



Photo 2 – Fuel spill and accident aircraft (courtesy of McLarens Claim Serv.)



Photo 3 – Bottom of left wing damage (Courtesy of McLarens Claim Serv.)



Photo 4 – Damaged left wing and ATV that was struck (Courtesy of McLarens Claim Serv.)