

RECORDING
TACH
TIME

TODAY'S
FLIGHT

TOTAL
TIME IN
SERVICE

Description of Inspections, Tests, Repairs and Alterations

Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

N4631J (Engine)

Piper PA-28R-180 S/N: 28R-30518

Engine M/N: IO-360-B1E

Daytona Aircraft Services, Inc.

S/N: L-6620-51A

4/8/2015

Tach: 6164.5

Eng TT: 6814.5

Eng TSMOH: 5.4

Performed the following maintenance:

1. Performed an Annual inspection referencing the Piper PA28R-180 Maintenance Manual.
2. Performed a compression test with the following results: #1 74/80, #2 76/80, #3 76/80, #4 77/80.
3. Drained the engine oil. Removed, cut open, and inspected the oil filter, no defects noted. Installed a new oil filter (P/N: AA48110) and serviced the engine with 8 quarts of Aeroshell 50W oil.
4. Complied with **AD 2011-26-04** by inspection of the fuel injector fuel lines, clamps, and the fuel injector nozzles ref. Lycoming Engines MSB No. 342G, no defects noted. Next due at **6264.5 Tach**.

I certify that this **Engine** has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition. Work performed in accordance with the current regulations of the FAA and is approved for return to service. Details are on file at this Repair Station under WO #10123.

Daytona Aircraft Services, Inc.

Daytona Beach, Florida

Authorized Signature:

FAA CRS DYTR262K

END

07/24/2015 10:11