



Photo 1 – Airplane at Accident Site (right side)



Photo 2 – Airplane at Accident Site (left side)



Photo 3 – Rust-Colored Debris and Water Drained from Accelerator Pump



Photo 4 – Rust Colored Debris and Water Drained from Accelerator Pump




Photo 5 - Water Drained from LH and RH Fuel Tanks