



Photo 1 – Balloon on Final Approach (Courtesy of Witness)



Photo 2 – Balloon During Landing Being Secured by Ground Crew (Courtesy of Witness)



Photo 3 – Balloon Draping Over Power Lines (Courtesy of Witness)



Photo 4 – Post Electrical Contact Smoke Surrounding Passenger Basket (Courtesy of Witness)



Photo 5 – Passenger Basket Looking South Southwest (Courtesy of FAA)



Photo 6 – Electrical Arc Burn on Basket Attach Cable (Courtesy of FAA)