



Photo 1 View of Initial Ground Scar (ILM Ops)–



Photo 2 – Tire Impressions and Skid Marks (ILM Ops)



Photo 3 – View of Main Wreckage as Found (ILM Ops)



Photo 4 – View of Main Wreckage as Found against Perimeter Fence (ILM Ops)



Photo 5 – View of Elevator Trim Tab Setting (ILM Ops)