



Photo 1 – View of airplane at accident site.



Photo 2 – Close up view of airplane, upside down in corn field.



Photo 3 –View of vertical stabilizer damage.



Photo 4 – View of bottom of airplane and nose gear damage.



Photo 5 – View of damaged number 4 cylinder and piston.