



Photo 1 – View of Helicopter following Accident (Operator)



Photo 2 – View of Disconnect Left Tail Rotor Pedal Control (Operator)



Photo 3 – View of Fractured Pin (Operator)



Photo 4 – View of Fractured Pin (Operator)