



Photo 1 – View of airplane prior to accident (Provided by FAA)



Photo 2 – View of fire damage to inboard left wing (Provided by FAA)



Photo 3 – View of fire damage to left engine nacelle (Provided by FAA)