



Photo 1 – View of nose and propeller (FAA photo)



Photo 2 - Aft view of wreckage (FAA photo)



Photo 3 - View of damaged fuselage (FAA photo)