



Photo 1 – Front Left Quartering View of Entire Glider and Damage (Courtesy of Pilot)



Photo 2 – Fuselage and Tail Damage; Tail Twisted to the Left (Courtesy of Pilot)



Photo 3 – Fuselage Aft of Wings Damage (Courtesy of Pilot)



Photo 4 – Hole in Ground that the Glider Struck (Courtesy of Pilot)