



Photo 1 – Cockpit looking Aft Towards Tail; Tail Twisted to the Left (Courtesy of FAA)



Photo 2 – Front Right Quartering View of Airplane Nose Down by Trees (Courtesy of FAA)



Photo 3 – Left Wing Damage (Courtesy of FAA)




Photo 4 – Right Wing and Fuselage Damage (Courtesy of FAA)



Photo 5 – Cockpit; Control Stick, Trim and Light Switches (Courtesy of FAA)