



Photo 1 – Main Wreckage (FAA Photo)



Photo 2 – Vertical Stabilizer and Rudder Damage



Photo 3 – Wing Buckling (FAA Photo)



Photo 4 – Wing Buckling (FAA Photo)



Photo 5 – Fuselage Damage (FAA Photo)