



Photo 1 – FAA Digital Photograph. Arrow Depicts the Reported Location of the Bush that the Right Wing Contacted



Photo 2 - FAA Digital Photograph. View Depicts the Bush that was Cut Postaccident that Reportedly was Contacted By the Right Wing



Photo 3 - FAA Digital Photograph. View Depicting the Damage to the Right Aileron