



Photo 1 – Left Profile of Airplane Showing Collapsed Nose Gear (Courtesy of FAA)



Photo 2 – Left Side of Fuselage Buckling. (Courtesy of FAA)



Photo 3 – Left Wing; Outboard Damage. (Courtesy of FAA)



Photo 4 – Close Up of Damaged Nose Gear and Fuselage. (Courtesy of FAA)