



Photo 1 – Pilot Taxiing Before Takeoff (Provided by Airplane Owner)



Photo 2 – Airplane In-flight After Takeoff (Provided by Airplane Owner)



Photo 3 – Main Wreckage View West-Southwest



Photo 4 – Main Wreckage View Northeast



Photo 5 – View of Main Wreckage View North



Photo 6 – Left Wing



Photo 7 – Right Wing and Main Wreckage



Photo 8 – Windshield Fragments (150 ft Northeast of Main Wreckage)



Photo 9 – Close-up of Larger Windshield Fragment (150 feet northeast of the main wreckage.



Photo 10 – Separated Propeller Blade



Photo 11 – Engine as it Came to Rest



Photo 12 – Engine During Recovery




Photo 13 – Top View of Engine



Photo 14 – Engine Cylinder Components



Photo 15 – Disassembled Engine Components