



Photo 1 – Accident Site, Immediate Vicinity and Damage



Photo 2 – Accident Site Broad View



Photo 3 – Left Wing Entire Top View of Damage



Photo 4 – Engine and Propeller Damage



Photo 6 – Elevator and Rudder looking Forward at Examination Hanger