



MEMORANDUM FOR RECORD

Douglass Brazy
Air Safety Investigator
Eastern Region Aviation

February 3, 2016

Subject: ERA16FA097, N401PT, Lancair IV-P, 01/30/16, Albany, Georgia, Review of Security Video

A review of airport security video revealed that during the takeoff roll (moving from the right to the left in this image), the airplane lifted off just as it passed the corner of a building in the foreground:




Figure 1 Security Video Image – Enlarged



Figure 2 Security Video Image – Full View

The GPS location of the camera was measured as:

31 31.889 N

84 11.307 W

Using a geographical information system overhead image of the airport, a line of sight was constructed from the camera location through the building corner, and extended to the runway centerline. The line of sight intersected the runway about 1,200 feet from the start of the runway.




Figure 3 - Overhead Image of Airport