



Photo 1 – Airplane Wreckage Left side



Photo 2 – Airplane Wreckage Right Side



Photo 3 - Engine



Photo 4 – Fuel Drained from Left Tank



Photo 5 – Fuel Drained from Right Tank



Photo 6 - Pilot's Lap belt Attach fitting (no grommet)



Photo 7 - Pilot's Lap belt Assembly (no grommet)



Photo 8 - Pilot's Shoulder Harness