



Photo 1 – NTSB Digital Photograph. View of the Cessna 340A Accident Site.



Photo 2 - NTSB Digital Photograph. View of the Cessna 340A Initial Impact Site. Note the Separated Propellers and ground scars from the left propeller and upper portion of the forward fuselage.



Photo 3 - NTSB Digital Photograph. Another View of the Cessna 340A Initial Impact Site. Note the fire damage to the Grass.



Photo 4 - NTSB Digital Photograph. Another View of the Cessna 340A Main Wreckage.



Photo 5 - NTSB Digital Photograph. Close-Up View of the Cessna 340A Main Wreckage. Note the Extensive Fire Damage.



Photo 6 - NTSB Digital Photograph. View of the Cessna 340A Aircraft Nose Section, Portion of Instrument Panel, Separated Instruments, and Cabin in Background. Note the Extensive Fire Damage.



Photo 7 – Textron Aviation Digital Photograph. View of the Left Propeller.



Photo 8 – NTSB Digital Photograph. View of the Right Propeller.

Friday, March 18, 2016 11:30:38 AM



Photo 9 - Video ScreenShot Capture as Cessna 172M First Came Into View on Runway 36.

Friday, March 18, 2016 11:30:44 AM



Photo 10 - Video ScreenShot Capture as Cessna 340A First Came Into View Over Runway 4, and Location of Cessna 172M.

Friday, March 18, 2016 11:30:44 AM



Photo 11 - Video ScreenShot Capture as Cessna 340A Began Climbing Left Turn, and Location of Cessna 172M.

Friday, March 18, 2016 11:30:46 AM



Photo 12 - Video ScreenShot Capture As Cessna 340A Increased Left Bank Angle, and Location of Cessna 172M.

Friday, March 18, 2016 11:30:47 AM



Photo 13 - Video ScreenShot Capture As Cessna 340A Began Descending, and Location of Cessna 172M.

Friday, March 18, 2016 11:30:48 AM



Photo 14 - Video ScreenShot Capture Of Cessna 340A Just Before Impact, and Location of Cessna 172M.



Photo 15 – Digital Photograph Provided by Owner/Operator of Cessna 172M. View of the Instrument Panel of Cessna 172M.