



Photo 1 – Main wreckage-inverted-right side-NTSB



Photo 2 – Main wreckage-inverted left side-NTSB



Photo 3 – Main Wreckage-Upright-NTSB



Photo 4 – Seat rail 11th hole impression marks– (Textron)




Photo 5 – seat rail impression marks on 11th hole – (Textron)



Photo 6 – Right seat, and seat tang- (Textron)