



Photo 1 – Left Front View of Airplane Damage



Photo 2 – Aft View of Airplane Damage Looking Forward



Photo 3 – Ground Scars Leading up to Airplane Wreckage



Photo 4 – Vertical Propeller Blade Slice in Ground Near Impact Site (Glove for Reference Only)



Photo 5 – UAS Overhead View of Accident Site and Wreckage