



Photo 1 – View of front of airplane from right side showing fire damage



Photo 2 – View of front of airplane from left side showing fire damage



Photo 3 – View from rear of airplane showing fire damage



Photo 4 – View of cabin section fire damaged



Photo 5 – View of stand of trees looking from departure end of runway