



Figure 1 View of the terrain and wreckage.



Figure 2 Portion of the right side of the horizontal stabilator along the debris path.




Figure 3 Front view of the wreckage.