



Photo 1 – Preaccident Image of N5940 (Front View) – Courtesy of FAA



Photo 2 - Preaccident Image of N5940 (Left Side View) – Courtesy of FAA



Photo 3 – N5940 after Coming to Rest – Courtesy of WMVFC



Photo 4 – Main Wreckage after Fire Extinguishment – Courtesy of WMVFC



Photo 5 – Burn Pattern after Wreckage Removal



Photo 6 – Ground Scars After Airplane Left the Runway



Photo 7 – Main Wreckage (Front View)



Photo 8 – Main Wreckage (Left Side View)



Photo 9 – Main Wreckage (Rear View)



Photo 10 – Main Wreckage (Right Side View)



Photo 11 - Preaccident Image of N5940 (Right Side View) – Courtesy of FAA



Photo 12 - Preaccident Image of Cockpit (Right Side) – Courtesy of FAA



Photo 13 – Area of Fire Origin



Photo 14 – Broom Strawing



Photo 15 – Sump Tank



Photo 16 – Front View of Sump Tank



Photo 17 – Fire Sleeved Hoses



Photo 18 – Close Up of Fire Sleeved Hoses