



Photo 1 – Aerial Photo of Accident Site – Courtesy of Alexandria Balloon Flights



Photo 2 – Main Wreckage – Right Side View



Photo 3 – Main Wreckage – Right Rear View



Photo 4 – Main Wreckage – Left Side View



Photo 5 – Right Wing Flap – Retracted Position



Photo 6 – Right Main Landing Gear – Extended Position



Photo 7 – Close Up of Right Wing Leading Edge



Photo 8 – Small Tree



Photo 9 – Propeller Strike on A Branch of The Small Tree



Photo 10 – Throttle, Propeller, and Mixture Controls



Photo 11 – Initial Impact Point Wing Leading Edge Ground Scars – Paint Enhanced



Photo 12 – Initial Impact Point Nose Section Ground Scars – Paint Enhanced



Photo 13 – First Propeller Blade



Photo 14 – Second Propeller Blade



Photo 15 – Second Propeller Blade Tip



Photo 16 – Propeller Strike Marks on Runway



Photo 17 – Close Up of Propeller Strike Marks on Runway



Photo 18 – Tire and Propeller Strike Marks on Runway



Photo 19 – Close Up of Tire Mark on Runway