



Photo 1 – Accident Site – Courtesy of University of Tennessee Police Department



Photo 2 – Main Wreckage – Courtesy of University of Tennessee Police Department



Photo 3 – Close Up View of Main Wreckage – Courtesy of University of Tennessee Police Department



Photo 4 – Front View of Main Wreckage – Courtesy of FAA



Photo 5 – Close Up View of Nose Section – Courtesy of FAA



Photo 6 – Right Side View of Nose Section – Courtesy of FAA



Photo 7 – Right Side View of Main Wreckage – Courtesy of FAA



Photo 8 – Close Up View of Right Side of Main Wreckage – Courtesy of FAA



Photo 9 – Left Side View of Main Wreckage – Courtesy of FAA



Photo 10 – Close Up View of Propeller



Photo 11 – Instrument Panel – Courtesy of Textron Aviation



Photo 12 – Fuel Selector



Photo 13 – Flap Handle – Courtesy of Textron Aviation




Photo 14 – Landing Gear Handle – Courtesy of Textron Aviation



Photo 15 – Throttle, Mixture, Auxiliary Fuel Pump, and Propeller Controls



Photo 16 – Pilot's Shoulder Harness



Photo 17 – Passenger’s Shoulder Harness