



**Photo 1 – View of main wreckage (courtesy of local authorities)**



**Photo 2 - View of fuselage inverted (courtesy of local authorities)**



**Photo 3 - View of damaged wing, fuselage (courtesy of local authorities)**



**Photo 4 - View of top of fuselage and wing (courtesy of local authorities)**