



Photo 1 – Front view of airplane-revealing damage to left and right wings



Photo 2 – View of right wing showing buckling upward



Photo 3 – View of empennage showing buckling on the fuselage and left elevator damage



Photo 4- Front view underside of airplane showing damage to the firewall