



Photo 1 – View of front of airplane from left side showing nose damage



Photo 2 - View of front of airplane from right side showing nose damage



Photo 3 – View of left side of fuselage showing buckling at wing root