



Photo 1 – View of accident helicopter with door missing



Photo 2 – View of upper door track



Photo 3 – View of lower door track



Photo 4 – View of broken door stop bracket



Photo 5 – View of recovered door




Photo 6 – View of door showing the missing door stop




Photo 7 – View of door rail arm



Photo 8 – View of upper rail arm