



Photo 1 – View of Cockpit and Cabin Area after Recovery (Lycoming)



Photo 2 – View of Empennage and Tail Section after Recovery (Lycoming)



Photo 3 – View of Left Wing after Recovery (Lycoming)



Photo 4 – View of Engine after Recovery (Lycoming)