



Photo 1 – Accident Site, Ground Impact Path and Wreckage (Courtesy of FAA)



Photo 2 – Front View of Airplane Wreckage at Accident Site (Courtesy of FAA)



Photo 3 – Left Side View of Airplane Damage at Accident Site (Courtesy of FAA)




Photo 4 – Right Rear View of Airplane Damage (Courtesy of Textron)