



Figure 1 Left rear view of the airplane resting against a tree (Photo courtesy of the FAA)



Figure 2 Left front view of the airplane and the separated engine to the right of the tree (Photo courtesy of the FAA)