



Photo 1 – FAA Digital Photograph. View Depicting the Inverted Airplane At The Accident Site. Note the Tree Limbs in the Foreground



Photo 2 - FAA Digital Photograph. View Depicting the Inboard Portion of the Fuselage Adjacent to the Cockpit. Note the Tree Limb near the Wing Strut



Photo 3 - FAA Digital Photograph. View Depicting the Airplane After Being Uprighted.