



Photo 1 – Photograph of runway taken from the departure end of 30. (Courtesy of FAA)



Photo 2 – Photograph of airplane in the trees. (Courtesy of FAA)



Photo 3 – View of right wing and strut damage. (Courtesy of FAA)



Photo 4 – View of left wing leading edge damage. (Courtesy of FAA)



Photo 5 – View of propeller damage. Note both blades are splintered on the outboard sections. (Courtesy of FAA)