



Photo 1 – Main Wreckage (FAA Photo)



Photo 2 – Vertical Stabilizer and Rudder (FAA Photo)



Photo 3 – Puncture Hole in Lower Engine Cowling (FAA Photo)



Photo 4 – Splintered Spray Pump Blade Sections (FAA Photo)




Photo 5 – Spray Pump (FAA Photo)




Photo 6 – Throttle Linkage (FAA Photo)