



Photo 1 – FAA Digital Photograph. Left Rear Quartering View of the Helicopter Following Recovery



Photo 2 - FAA Digital Photograph. Left Side View of the Helicopter Following Recovery



Photo 3 - FAA Digital Photograph. Right Forward Quartering View of the Helicopter Following Recovery



Photo 4 - FAA Digital Photograph. View of the Landing Gear Dampers Following Removal