



Photo 1 – Main Wreckage (FAA)



Photo 2 – Unapproved fuel line




Photo 3 – loose fuel line with fuel leaking