



Photo 1 – View of Airplane As Found (FAA)



Photo 2 – Quartering View of Airplane as Found (FAA)




Photo 3 – View of Exemplar Landing Gear Actuator Retracted Position (Textron)




Photo 4 - View of Exemplar Landing Gear Actuator Extended Position (Textron)



Photo 5 - View of Accident Landing Gear Actuator as Found (FAA)




Photo 6 – Close-up View of Actuator as Found (FAA)