



Photo 1 – View of Main Wreckage (FAA)



Photo 2 – View of Cockpit Area (FAA)



Photo 3 – View of Engine (FAA)



Photo 4 – View of Leading Edge of Left Wing (FAA)



Photo 5 – View of Propeller Spinner (FAA)



Photo 6 – View of Initial Ground Scar (FAA)



Photo 7 – View of Tree Line Entry Point Adjacent to Runway (FAA)



Photo 8 – View of Angular Cut in Branch Above Crash Site (FAA)