



Photo 1 – Main Wreckage (Eustis FL Police Photo)



Photo 2 – Spar Damage (Eustis FL Police Photo)



Photo 3 – Damage to Residence (Eustis FL Police Photo)