



Photo 1 – Airplane immediately after impact showing post-crash fire. (Courtesy of Operator)



Photo 2 – Right side of airplane showing damage. (Courtesy of FAA)



Photo 3 – View of right side of airplane showing damage. (Courtesy of FAA)



Photo 4 – View of trailer impact damage. (Courtesy of FAA)



**Photo 5 – Right side of radial engine damage. Note cylinders shown are number 1 on top through number 4 on bottom.
(Courtesy of FAA)**



Photo 6 – Closeup of number 3 cylinder damage. (Courtesy of FAA)



Photo 7 – Additional closeup of number 3 cylinder damage. (Courtesy of FAA)