



Photo 1 – View of left side of airplane



Photo 2 – View of engine separated from firewall on left side showing heavy damage



Photo 3 – Front view of engine under airplane showing firewall damage



Photo 4 – View of damaged radial engine



Photo 5 – View of part of the propeller and engine lodged under the damaged fuselage.