



Photo 1 – Front Left Fuselage and Wing Damage (Photograph Courtesy of FAA)



Photo 2 – Skid Marks on Ground and Left View of Airplane (Photograph Courtesy of FAA)



Photo 3 – Close up of Left Side of Airplane Damage (Photograph Courtesy of FAA)