




Photo 1 – Main Wreckage – Courtesy of FAA



Photo 2 – Close Up of Main Wreckage – Courtesy of FAA



Photo 3 – Left Side of Main Wreckage – Courtesy of FAA



Photo 4 – Emergency Exit Window – Courtesy of FAA



Photo 5 – Interior View of Emergency Exit Window – Courtesy of FAA



Photo 6 – Aft Portion of Emergency Exit Window Latching Mechanism – Courtesy of FAA



Photo 7 – Forward Portion of Emergency Exit Window Latching Mechanism – Courtesy of FAA