



Figure 1 Front view of the airplane with trees on the approach path behind the airplane



Figure 2 Engine and propeller



Figure 3 Front view of airplane, dent on the right wing leading edge