



Photo 1 – Front left Quartering View of Airplane (Courtesy of FAA)



Photo 2 – Left Rear View of Airplane with Vertical Stabilizer and Gear Damage (Courtesy of FAA)



Photo 3 – Right Elevator and Vertical Stabilizer Damage (Courtesy of FAA)



Photo 4 – Runway and Grass Skid Marks Leading up to Airplane (Courtesy of FAA)